

Project Name: Budapest One  
Project ID: 38196

**FUTUREAL**

## Quarterly Water Testing

| Budapest ONE Phase I.      |                                                |                          |                          |                          |                          |                              |                                        |                                           |
|----------------------------|------------------------------------------------|--------------------------|--------------------------|--------------------------|--------------------------|------------------------------|----------------------------------------|-------------------------------------------|
| Dátum / Date               | Mintavétel helye / Sampling point              | Arzén / Arsenic [mg/L]   | Higany / Mercury [mg/L]  | Ólom / Lead [mg/L]       | Réz / Copper [mg/L]      | Zavarosság / Turbidity [NTU] | Összes kólibaktérium / Total coliforms | TESTING PERFORMED BY                      |
| Maximum határérték / Limit |                                                | 0.01 mg/L.               | 0.002 mg/L.              | 0.01 mg/L                | 1.0 mg/L.                | 1.0 NTU.                     | 0 CFU / not detected                   |                                           |
| Frequency / Gyakoriság     |                                                | quarterly / Negyedévente | quarterly / Negyedévente | quarterly / Negyedévente | quarterly / Negyedévente | quarterly / Negyedévente     | Negyedévente / quarterly               |                                           |
|                            | Prior WELL Certification                       |                          |                          |                          |                          |                              |                                        |                                           |
| 01/17/2022                 | Tower B ground floor restroom                  | 0,0016                   | 0,0002                   | 0,0005                   | 0                        | 0                            | 0 (Municipal test)                     | Wessling Hungary Kft.                     |
| 04/22/2022                 | Tower B ground floor restroom                  | 0,0016                   | 0,0002                   | 0,0005                   | 0,0137                   | 0                            | 0 (Municipal test)                     | Wessling Hungary Kft.                     |
| 07/18/2022                 | Tower A ground floor restroom                  | 0,0019                   | 0,0002                   | 0,0021                   | 0,0601                   | 0                            | 0 (Municipal test)                     | Wessling Hungary Kft.                     |
|                            | During WELL Certification:                     |                          |                          |                          |                          |                              |                                        |                                           |
| 10/28/2022                 | Tower B ground floor restroom                  | 0,0018                   | 0,0002                   | 0,0005                   | 0,0026                   | 0                            | 0 (Municipal test)                     | Wessling Hungary Kft.                     |
| 12/13-22/2022              | Tower B ground floor restroom                  | 0,0017                   | 0,0002                   | 0,0146                   | 0,3650                   | 0                            | 0 (Municipal test)                     | Wessling Hungary Kft.                     |
| 02/08-23/2023              | Tower A - P1, FM Team changing room            | 0,0016                   | 0,0002                   | 0,0011                   | 0,0268                   | 0,82                         | 0                                      | Eurofins Analytical Services Hungary Kft. |
|                            | Tower B - P2 Bicycle changig room              | 0,0015                   | 0,0002                   | 0,0023                   | 0,0487                   | 0,75                         | 0                                      |                                           |
|                            | Tower A - Ground Floor Lobby - Restroom        | 0,0016                   | 0,0002                   | 0,0022                   | 0,0715                   | 0,39                         | 0                                      |                                           |
|                            | Tower B - Ground Floor Lobby - Restroom        | 0,0015                   | 0,0002                   | 0,0005                   | 0,0152                   | 0,45                         | 0                                      | Eurofins Analytical Services Hungary Kft. |
|                            | Tower B - Water dispenser                      | 0,0011                   | 0,0002                   | 0,0005                   | 0,0005                   | 0,63                         | 0                                      |                                           |
|                            | Tower A - Ground Floor Lobby - Water dispenser | 0,0005                   | 0,0002                   | 0,0005                   | 0,0005                   | 0,65                         | 0                                      |                                           |
| 06/08-16/2023              | Tower B - Ground Floor Lobby - Restroom        | -                        | -                        | -                        | -                        | 0,28                         | 0                                      | Eurofins Analytical Services Hungary Kft. |
|                            | Tower B - Water dispenser - rooftop            | -                        | -                        | -                        | -                        | 0,44                         | 0                                      |                                           |
|                            | Tower B - P2 Bicycle changig room              | -                        | -                        | -                        | -                        | 0,37                         | 0                                      |                                           |
|                            | Tower A - Water dispenser - rooftop            | 0,0014                   | 0,0002                   | 0,0005                   | 0,001                    | -                            | -                                      | Eurofins Analytical Services Hungary Kft. |
|                            | Tower A - P1, FM Team changing room            | 0,0017                   | 0,0002                   | 0,0015                   | 0,0513                   | -                            | -                                      |                                           |
|                            | Tower A - Well room                            | 0,0017                   | 0,0002                   | 0,0007                   | 0,0058                   | -                            | -                                      |                                           |
| 10/19/2023                 | Tower A - Well room                            | 0,0017                   | 0,0002                   | 0,0005                   | 0,007                    | -                            | -                                      | Eurofins Analytical Services Hungary Kft. |
|                            | Tower B - Ground Floor Lobby - Restroom        | -                        | -                        | -                        | -                        | 0,46                         | 0                                      |                                           |
|                            | Tower B - Water dispenser - rooftop            | 0,0005                   | 0,0002                   | 0,0005                   | 0,0005                   | 0,33                         | 0                                      |                                           |
|                            | Tower B - P2 Bicycle changig room              | -                        | -                        | -                        | -                        | 0,25                         | 0                                      |                                           |
|                            | Tower A - P1, FM Team changing room            | 0,0018                   | 0,0002                   | 0,0011                   | 0,034                    | -                            | -                                      |                                           |
|                            |                                                |                          |                          |                          |                          |                              |                                        |                                           |
|                            |                                                |                          |                          |                          |                          |                              |                                        |                                           |
|                            |                                                |                          |                          |                          |                          |                              |                                        |                                           |
|                            |                                                |                          |                          |                          |                          |                              |                                        |                                           |