

Project Name: Budapest One Business Park Phase II.
Project ID: 1201910580



Quarterly Water Testing

The below schedule addresses the requirements of optimization Feature 35, part 1 in the WELL Building Standard v1 and for Innovation: v2 pilot [W01.3 c & W02.7 c]=W05

FEATURE 35: PERIODIC WATER QUALITY TESTING and for Innovation: v2 pilot [W01.3 c & W02.7 c]=W05
See measurable water parameters and frequency below. See the required number of the sampling points in "Mintavételi pontok száma" spreadsheet (5% of the total number of fixtures per configuration is required to measure (max. 4 fixture per configuration) - water dispenser with filter counts as different water treatment compared to unfiltered main supply-water

Budapest ONE Phase II.								
Dátum / Date	Mintavétel helye / Sampling point	Arzén / Arsenic [mg/L]	Higany / Mercury [mg/L]	Ólom / Lead [mg/L]	Réz / Copper [mg/L]	Zavarosság / Turbidity [NTU]	Összes kólbaktérium / Total coliforms	TESTING PERFORMED BY
Maximum határérték / Limit		0.01 mg/L	0.002 mg/L	0.01 mg/L	1.0 mg/L	1.0 NTU	0 CFU / not detected	
Maximum határérték - számmal		0,01	0,002	0,01	1	1	0	
Maximum határérték		10 microgram / dm3	2 microgram / dm3	10 microgram / dm3	1000 microgram / dm3	1	0 / not detected	
Frequency / Gyakoriság		quarterly / Negyedévente	quarterly / Negyedévente	quarterly / Negyedévente	quarterly / Negyedévente	quarterly / Negyedévente	Negyedévente / quarterly	
Mintavételi pontok száma és/ vagy helye	3+1							
Reasons to measure		v1 F35	v1 F35	v1 F35 & Innovation: v2 pilot W05	v1 F35 & Innovation: v2 pilot W05	Innovation: v2 pilot W05	Innovation: v2 pilot W05	
YYYY/MM/DD								
Sampling date: 2025 08 19	Laboratory assesment was finalised on 28th August, 2025							
Documentation date for coliforms: 2025 08 22	Rooftop water dispenser	0,0011	<0,0002	<0,0005	<0,0005	<0,25	0	Sampling and metalloids, PH, and turbidity: Eurofins Analytical Services Hungary Kft. Coliforms: Eurofins Food and Feed Testing Budapest Kft.
	8th floor restroom	0,0015	<0,0002	0,0010	0,0160	<0,25	0	
Documentation date for metalloids: 2025 08 28	Ground floor disabled restroom /accessible washroom	0,0017	<0,0002	0,0077	0,1950	<0,25	0	
	P2 bicycle restroom - female	0,0016	<0,0002	0,0025	0,0600	<0,25	0	
Sampling date: 2025 11 28	Laboratory assesment was finalised on 9th December, 2025							
Documentation date for coliforms: 2025 12 02	Rooftop water dispenser	0,0015	<0,0002	<0,0005	<0,0005	<0,25	0	Sampling and metalloids, PH, and turbidity: Eurofins Analytical Services Hungary Kft. Coliforms: Eurofins Food and Feed Testing Budapest Kft.
	8th floor restroom, female, #2	0,0018	<0,0002	0,0025	0,1050	<0,25	0	
Documentation date for metalloids: 2025 12 09	Ground floor disabled restroom	0,0017	<0,0002	0,0011	0,0412	<0,25	0	
	3rd floor restroom, female, #2	0,0018	<0,0002	0,0025	0,1050	<0,25	0	
Sampling date: 2026 03 12	3rd floor women's washroom #2	0,0016	<0,0002	<0,0012	<0,02	0,47	0	Sampling and metalloids, PH, and turbidity: Eurofins Analytical Services Hungary Kft. Coliforms: Eurofins Food and Feed Testing Budapest Kft.
	8th floor women's washroom #2	0,0015	<0,0002	0,0022	0,0370	<0,25	0	
Documentation date for coliforms: 2026 03 16	Rooftop water dispenser	0,0009	<0,0002	0,0005	0,0010	<0,25	0	
Documentation date for metalloids: 2026 03 20	ground floor accessible washroom	0,0015	<0,0002	0,0011	0,0550	<0,25	0	
Sampling date: 2026 06 05	3rd floor women's washroom #1	0,0016	<0,0002	0,0012	0,0118	<0,25	0	Sampling and metalloids, PH, and turbidity: Eurofins Analytical Services Hungary Kft. Coliforms: Eurofins Food and Feed Testing Budapest Kft.
	8th floor women's washroom #1	0,0015	<0,0002	0,0008	0,0152	<0,25	0	
Documentation date for coliforms: 2026 03 16	Rooftop water dispenser	0,0008	<0,0002	<0,0005	0,0005	<0,25	0	
Documentation date for metalloids: 2026 06 16	ground floor accessible washroom	0,0015	<0,0002	<0,0005	0,0057	<0,25	0	