

Project name: Budapest One Business Park Phase III.
Project ID: 1201910581



F35 & F105 Quarterly Water Testing

The below schedule addresses the requirements of optimization Feature 35, part 1 in the WELL Building Standard v1 and for Innovation: v2 pilot [W01.3 c & W02.7 c]=W05

FEATURE 35: PERIODIC WATER QUALITY TESTING and for Innovation: v2 pilot [W01.3 c & W02.7 c]=W05
See measurable water parameters and frequency below. Tested parameters: arsenic, mercury, lead, coper, turbidity, coliforms Sampling points: 1 pc of filtered water, 3 pcs of unfiltered main supply water For further information, see the required number of the sampling points in ""Mintavételi pontok száma"" spreadsheet (5% of the total number of fixtures per configuration is required to measure (max. 4 fixture per configuration) - water dispenser with filter counts as different water treatment compared to unfiltered main supply-water

Budapest ONE Phase III.								
Dátum / Date	Mintavétel helye / Sampling point	Arzén / Arsenic [mg/L]	Higany / Mercury [mg/L]	Ólom / Lead [mg/L]	Réz / Copper [mg/L]	Zavarosság / Turbidity [NTU]	Összes kólibaktérium / Total coliforms	TESTING PERFORMED BY
Maximum határérték / Limit		0.01 mg/L	0.002 mg/L	0.01 mg/L	1.0 mg/L	1.0 NTU	0 CFU / not detected	
Frequency / Gyakoriság		quarterly / Negyedévente	quarterly / Negyedévente	quarterly / Negyedévente	quarterly / Negyedévente	quarterly / Negyedévente	Negyedévente / quarterly	
Mintavételi pontok száma és/ vagy helye	3+1							
Reasons to measure		v1 F35 & Innovation: v2 pilot W05	v1 F35 & Innovation: v2 pilot W05	v1 F35 & Innovation: v2 pilot W05	v1 F35 & Innovation: v2 pilot W05	Innovation: v2 pilot W05	Innovation: v2 pilot W05	
DD/MM/YYYY								
Sampling date: 2025 08 19	Rooftop water dispenser	0,0012	<0,0002	<0,0005	<0,0005	0,25	0	Sampling and metalloids, PH, and turbidity: Eurofins Analytical Services Hungary Kft. Coliforms: Eurofins Food and Feed Testing Budapest Kft.
Documentation date for coliforms: 2025 08 22	8th floor restroom	0,0017	<0,0002	0,0008	0,0184	0,25	0	
Documentation date for metalloids: 2025 08 28	Ground floor disabled restroom	0,0015	<0,0002	0,0010	0,0083	0,25	0	
Sampling date: 2025 12 01	Rooftop water dispenser	0,0015	<0,0002	<0,0005	<0,0005	<0,25	0	Sampling and metalloids, PH, and turbidity: Eurofins Analytical Services Hungary Kft. Coliforms: Eurofins Food and Feed Testing Budapest Kft.
Documentation date for coliforms: 2025 12 12	8th floor restroom, female, #2	0,0018	<0,0002	0,0025	0,1050	<0,25	0	
Documentation date for metalloids: 2025 12 09	Ground floor disabled restroom	0,0017	<0,0002	0,0011	0,0412	<0,25	0	
	3rd floor restroom, female, #2	0,0018	<0,0002	0,0025	0,1050	<0,25	0	
Sampling date: 2026 03 12	Rooftop water dispenser	0,0012	<0,0002	<0,0005	0,0010	<0,25	0	Sampling and metalloids, PH, and turbidity: Eurofins Analytical Services Hungary Kft. Coliforms: Eurofins Food and Feed Testing Budapest Kft.
Documentation date for coliforms: 2026 03 16	8th floor restroom, male, #2	0,0017	<0,0002	0,0008	0,0230	0,4	0	
Documentation date for metalloids: 2026 03 20	4th floor restroom, male, #2	0,0016	<0,0002	0,0025	0,0380	0,48	0	
	P1 - bicycle changing room, male, #1	0,0014	<0,0002	0,0016	0,0760	0,28	0	
Sampling date: 2026 06 05	Rooftop water dispenser	0,0013	<0,0002	<0,0005	<0,0005	<0,25	0	Sampling and metalloids, PH, and turbidity: Eurofins Analytical Services Hungary Kft. Coliforms: Eurofins Food and Feed Testing Budapest Kft.
Documentation date for coliforms: 2026 06 08	8th floor restroom, female, #1	0,0016	<0,0002	0,0021	0,0540	<0,25	0	
Documentation date for metalloids: 2026 06 15	3rd floor restroom, female, #1	0,0012	<0,0002	0,0022	0,0687	<0,25	0	
	Ground floor disabled restroom	0,0016	<0,0002	0,0022	0,0579	<0,25	0	